EXHIBIT B

IYS Ventures, LLC

Estimated Repair Costs Projected as of

8/13/2024

Site	Maintenace	Estir	Estimated Cost		Total Site Costs	
IL0097	Walk-in cooler	\$	8,500.00			
IL0097		\$	-	\$	8,500.00	
IL0087		\$	-			
MN0018	Cooler	\$	10,000.00			
	HVAC	\$	35,000.00			
	Fountain/ice maker	\$	4,250.00			
	Open air equipment	\$	10,000.00			
MN0018		\$	-	\$	59,250.00	
WI0003	Exterior lighting	\$	5,200.00			
	Interior/cooler lighting	\$	1,500.00			
	Ceiling tile replacement	\$	800.00			
WI0003	-	\$	-	\$	7,500.00	
WI0005	HVAC system as a whole	\$	35,000.00			
	Exterior lighting	\$	6,000.00			
	Interior/cooler lighting	\$	1,500.00			
	Restroom repairs	\$	100.00			
WI0005	Water heater	\$	1,200.00	\$	43,800.00	
WI0063	Interior/cooler lighting	\$	1,500.00		•	
	Exterior lighting	\$	6,000.00			
	Water heater	\$	1,200.00			
	Ceiling tiles/water leak	\$	1,800.00			
WI0063	-	\$	-	\$	10,500.00	
MN0045	Exterior lighting	\$	6,000.00			
	Interior/cooler lighting	\$	1,500.00			
MN0045		\$	-	\$	7,500.00	
SD0002		\$	-	\$	-	
SD0004		\$	-	\$	-	
MS0004		\$	-	\$	-	
MS0005		\$	-	\$	-	
LA0054		\$	-	\$	-	
LA0053		\$	-	\$	-	
LA0058		\$	-	\$	-	
OH0088		\$	-	\$	-	
OH0077		\$	-	\$	-	
OH0095		\$	-	\$	-	
OH0030		\$	-	\$	-	
OH0048		\$	-	\$	-	
OH0100		\$	-	\$	-	
WI0057		\$	-	\$	-	
MI0001	Perimeter lights out	\$	5,200.00			
	Interior/cooler lighting	\$	1,500.00			
	W/I cooler condenser	\$	6,000.00			

	Restroom plumbing	\$ 1,800.00		
	Building damage repair ACM	\$ 2,500.00		
MI0001		\$ -	\$	17,000.00
MI0002	Pump repairs	\$ 2,100.00	<u> </u>	17,000.00
14110002	W/I cooler down	\$ 2,500.00		
	Perimeter lights out	\$ 5,200.00		
		\$ 1,000.00		
	Soffit lighting out			
	Cooler lights out	\$ 550.00		
	Stained tiles	\$ 800.00		
MI0002		\$ <u>-</u>	\$	12,150.00
MN0039	Pump repairs	\$ 1,500.00		
	Broken window	\$ 1,200.00		
	R/I cooler not working	\$ 1,600.00		
	Interior/cooler lighting	\$ 1,200.00		
	Stained tiles	\$ 800.00		
	Roof repair	\$ 4,000.00		
	Open air equipment	\$ 6,000.00		
MN0039		\$ _	\$	16,300.00
WI0054	Safe is broken	\$ 2,500.00		•
	Heat not working	\$ 10,000.00		
	Compress w/i cooler replaced	\$ 6,000.00		
	Perimeter lights out	\$ 5,200.00		
	Stained tiles	\$ 800.00		
		\$		
14/1005	ATG not working	1,500.00		26.000.00
WI0054		\$ -	\$	26,000.00
MN0002	Perimeter lights out	\$ 5,200.00		
	Interior/cooler lighting	\$ 1,200.00		
	Stained tiles	\$ 800.00		
	RR broken mirror	\$ 100.00		
	Car wash vac/paysation not working	\$ 2,000.00		
		\$ -		
MN0002	Fire extinguishers out of date	\$ 100.00	\$	9,300.00
MN0006	Pump down struck by truck	\$ 15,000.00		
	Pump printers replaced - 2	\$ 3,500.00		
	Interior/cooler lighting	\$ 1,200.00		
	Exit door repair	\$ 250.00		
	Filters changed	\$ 200.00		
	Repair door	\$ 100.00		
MN0006		\$ 100.00	\$	20.250.00
MN0008		\$ E 200.00	٦	20,350.00
MUUUUX	Perimeter lights out	5,200.00		
8.4510.000	Pin pads replaced - several	\$ 6,000.00	_	44 000 00
MN0008		\$ -	\$	11,200.00
MN0009	Pump repairs	\$ 150.00		
	Interior/cooler lighting	\$ 1,200.00		
	Fire extinguishers out of date	\$ 100.00		
MN0009		\$ -	\$	1,450.00
MN0010	Perimeter lights out	\$ 5,200.00		

Cooler lights out Floor issue MN0010 MN0023 Perimeter lights out Exit door not functional Car wash not working AC filters changed MN0023 MN0025 MID repaired not working on one side Interior/cooler lighting Window replacement RR exhaust fan/faucet replaced R/I freezer not working MN0025 MN0026 Perimeter lights out Interior/cooler lighting Air does not work MN0026 MN0030 Perimeter lights out Exit door doesn't function	\$ 800.00 \$ 2,500.00 \$ - \$ 5,200.00 \$ 900.00 \$ 10,000.00 \$ 200.00 \$ - \$ 2,500.00 \$ 1,200.00 \$ 1,200.00 \$ 6,000.00 \$ 5,200.00 \$ 5,200.00 \$ 5,200.00 \$ 5,200.00	\$ 16,300
MN0010 MN0023 Perimeter lights out Exit door not functional Car wash not working AC filters changed MN0023 MN0025 MID repaired not working on one side Interior/cooler lighting Window replacement RR exhaust fan/faucet replaced R/I freezer not working MN0025 MN0026 Perimeter lights out Interior/cooler lighting Air does not work MN0026 MN0030 Perimeter lights out	\$ 5,200.00 \$ 900.00 \$ 10,000.00 \$ 200.00 \$ - \$ 2,500.00 \$ 1,200.00 \$ 1,200.00 \$ 300.00 \$ 6,000.00 \$ 5,200.00 \$ 1,200.00 \$ -	\$ 16,300
MN0023 Perimeter lights out Exit door not functional Car wash not working AC filters changed MN0023 MN0025 MID repaired not working on one side Interior/cooler lighting Window replacement RR exhaust fan/faucet replaced R/I freezer not working MN0025 MN0026 Perimeter lights out Interior/cooler lighting Air does not work MN0026 MN0030 Perimeter lights out	\$ 5,200.00 \$ 900.00 \$ 10,000.00 \$ 200.00 \$ - \$ 2,500.00 \$ 1,200.00 \$ 1,200.00 \$ 6,000.00 \$ - \$ 5,200.00 \$ 1,200.00 \$ -	\$ 16,300
Exit door not functional Car wash not working AC filters changed MN0023 MN0025 MID repaired not working on one side Interior/cooler lighting Window replacement RR exhaust fan/faucet replaced R/I freezer not working MN0025 MN0026 Perimeter lights out Interior/cooler lighting Air does not work MN0026 MN0030 Perimeter lights out	\$ 900.00 \$ 10,000.00 \$ 200.00 \$ - \$ 2,500.00 \$ 1,200.00 \$ 1,200.00 \$ 6,000.00 \$ - \$ 5,200.00 \$ 1,200.00 \$ -	
Car wash not working AC filters changed MN0023 MN0025 MID repaired not working on one side Interior/cooler lighting Window replacement RR exhaust fan/faucet replaced R/I freezer not working MN0025 MN0026 Perimeter lights out Interior/cooler lighting Air does not work MN0026 MN0030 Perimeter lights out	\$ 10,000.00 \$ 200.00 \$ - \$ 2,500.00 \$ 1,200.00 \$ 1,200.00 \$ 300.00 \$ 6,000.00 \$ 5,200.00 \$ 1,200.00 \$ - \$ 5,200.00	
AC filters changed MN0023 MN0025 MID repaired not working on one side Interior/cooler lighting Window replacement RR exhaust fan/faucet replaced R/I freezer not working MN0025 MN0026 Perimeter lights out Interior/cooler lighting Air does not work MN0026 MN0030 Perimeter lights out	\$ 200.00 \$ - \$ 2,500.00 \$ 1,200.00 \$ 1,200.00 \$ 300.00 \$ 6,000.00 \$ - \$ 5,200.00 \$ 1,200.00 \$ 500.00 \$ -	
MN0023 MN0025 MID repaired not working on one side Interior/cooler lighting Window replacement RR exhaust fan/faucet replaced R/I freezer not working MN0025 MN0026 Perimeter lights out Interior/cooler lighting Air does not work MN0026 MN0030 Perimeter lights out	\$ - \$ 2,500.00 \$ 1,200.00 \$ 1,200.00 \$ 300.00 \$ 6,000.00 \$ - \$ 5,200.00 \$ 1,200.00 \$ 500.00 \$ -	
MN0025 MID repaired not working on one side Interior/cooler lighting Window replacement RR exhaust fan/faucet replaced R/I freezer not working MN0025 MN0026 Perimeter lights out Interior/cooler lighting Air does not work MN0026 MN0030 Perimeter lights out	\$ - \$ 2,500.00 \$ 1,200.00 \$ 1,200.00 \$ 300.00 \$ 6,000.00 \$ - \$ 5,200.00 \$ 1,200.00 \$ 500.00 \$ -	
Interior/cooler lighting Window replacement RR exhaust fan/faucet replaced R/I freezer not working MN0025 MN0026 Perimeter lights out Interior/cooler lighting Air does not work MN0026 MN0030 Perimeter lights out	\$ 2,500.00 \$ 1,200.00 \$ 1,200.00 \$ 300.00 \$ 6,000.00 \$ - \$ 5,200.00 \$ 1,200.00 \$ 500.00 \$ -	
Interior/cooler lighting Window replacement RR exhaust fan/faucet replaced R/I freezer not working MN0025 MN0026 Perimeter lights out Interior/cooler lighting Air does not work MN0026 MN0030 Perimeter lights out	\$ 1,200.00 \$ 1,200.00 \$ 300.00 \$ 6,000.00 \$ - \$ 5,200.00 \$ 1,200.00 \$ 500.00 \$ -	\$ 11,200
Window replacement RR exhaust fan/faucet replaced R/I freezer not working MN0025 MN0026 Perimeter lights out Interior/cooler lighting Air does not work MN0026 MN0030 Perimeter lights out	\$ 1,200.00 \$ 300.00 \$ 6,000.00 \$ - \$ 5,200.00 \$ 1,200.00 \$ 500.00 \$ -	\$ 11,200
RR exhaust fan/faucet replaced R/I freezer not working MN0025 MN0026 Perimeter lights out Interior/cooler lighting Air does not work MN0026 MN0030 Perimeter lights out	\$ 300.00 \$ 6,000.00 \$ - \$ 5,200.00 \$ 1,200.00 \$ 500.00 \$ -	\$ 11,200
R/I freezer not working MN0025 MN0026 Perimeter lights out Interior/cooler lighting Air does not work MN0026 MN0030 Perimeter lights out	\$ 6,000.00 \$ - \$ 5,200.00 \$ 1,200.00 \$ 500.00 \$ -	\$ 11,200
MN0025 MN0026 Perimeter lights out Interior/cooler lighting Air does not work MN0026 MN0030 Perimeter lights out	\$ - \$ 5,200.00 \$ 1,200.00 \$ 500.00 \$ -	\$ 11,200
MN0026 Perimeter lights out Interior/cooler lighting Air does not work MN0026 MN0030 Perimeter lights out	\$ 5,200.00 \$ 1,200.00 \$ 500.00 \$ -	\$ 11,200
Interior/cooler lighting Air does not work MN0026 MN0030 Perimeter lights out	\$ 1,200.00 \$ 500.00 \$ -	
Air does not work MN0026 MN0030 Perimeter lights out	\$ 500.00 \$ -	
MN0026 MN0030 Perimeter lights out	\$ -	
MN0030 Perimeter lights out		•
<u> </u>	5 200 00	\$ 6,900
Exit door doesn't function	7 3,200.00	
	\$ 200.00	
Stained tiles	\$ 800.00	
AC filters changed	\$ 200.00	
Service air compressor - interior	\$ 3,000.00	
W/I cooler not working	\$ 6,000.00	
Air out of order	\$ 500.00	
R/I freezers not working - 3		
MN0030		\$ 22,000
	\$ -	\$ 33,900
MN0041 Perimeter lights out	\$ 5,200.00	
Cooler lights out	\$ 800.00	
Roof leaks	\$ 10,000.00	
Stained tiles	\$ 800.00	
Cracked window	\$ 1,200.00	
MN0041	\$ -	\$ 18,000
WI0010 Perimeter lights out	\$ 5,200.00	
Pump repairs needed	\$ 1,700.00	
Interior/cooler lighting	\$ 1,200.00	
Roof leaks	\$ 10,000.00	
Stained tiles	\$ 800.00	1
WI0010	\$ -	\$ 18,900
WI0062 Perimeter lights out		7 18,500
		+
Pole light damaged	\$ 2,000.00	
Price sign not working	\$ 1,200.00	1
Interior/cooler lighting	\$ 1,200.00	
Stained tiles	\$ 800.00	
AC filters changed	\$ 200.00	
Open air not working	\$ 6,000.00	
WI0062	\$ -	\$ 16,600

VA0452	Dispenser hit, needs replaced/repaired	\$ 15,000.00	
	Pump repairs	\$ 1,200.00	
	Interior/cooler lighting	\$ 1,200.00	
	Fire extinguishers out of date	\$ 100.00	
VA0452		\$ -	\$ 17,500.00
TOTAL		\$ 398,600.00	\$ 398,600.00